Ministry of Tourism, Culture and Sport

Culture Services Unit Programs and Services Branch Culture Division 401 Bay Street, Suite 1700 Toronto ON M7A 0A7 Tel.: 416 314-3108 Fax: 416 314-7175 Ministère du Tourisme, de la Culture et du Sport

Unité des services culturels Direction des programmes et des services Division de culture 401, rue Bay, bureau 1700 Toronto ON M7A 0A7 Tél. : 416 314-3108 Téléc. : 416 212-7175



June 11, 2012

Mr. Simon Kim Kingston Solar LP 55 Standish Court, 9th Floor Mississauga, ON L5R 4B2

RE: Sol-luce Kingston Solar PV Energy Project

Location: Multiple lots, City of Kingston and Loyalist Township

MTC DPR file no.: PLAN-00EA071

Dear Mr. Kim:

This letter constitutes the Ministry of Tourism, Culture and Sport's written comments as required by s. 23(3)(a) of O. Reg. 359/09 under the *Environmental Protection Act* regarding heritage assessments undertaken for the above project.

Based on the information contained in the report you have submitted for this project, the Ministry is satisfied with the heritage assessment. Please note that the Ministry makes no representation or warranty as to the completeness, accuracy or quality of the heritage assessment report.

The report recommends the following:

4.0 CONCLUSIONS

Protected properties

As a result of consultation with designating authorities under the Ontario Heritage Act, none of the identified properties constitute protected properties under Ontario Regulation 359/09.

Cultural heritage value

It is concluded that while all the properties exhibit varying degrees of association with the historical theme of land settlement and related agricultural activity, (namely they are remnant agricultural fields in a larger contextual rural landscape) and possess some contextual value due to historical linkages with their surroundings, none are of sufficient cultural heritage value or interest that would warrant not-developing these lands for solar energy facility.

Mitigation of effects in interior properties

Impacts to heritage resources may be short or long in duration and experienced during construction only or during the post construction phase. Where interior properties (i.e., those without direct road frontage) are proposed to be developed for solar energy purposes these properties are considered to have less visual exposure within the rural landscape, such as the eastern side of Quabbin Road. Existing vegetation and screening for the most part will provide visual buffering or filtering of extended views to these properties from the public road right-of way and should be protected and retained.

Although not required for interior properties with some degree of visual buffering or filtering, additional visual buffering will be considered for interior properties as detailed design proceeds.

Mitigation of effects in properties adjacent to road rights-of –way

At those locations adjacent to a road right of way, (Unity Road, the south side of Mud Lake Road, the west side of Howes Road, the north side of Rock Road, and the west side of Highway 38) the solar facility may be open to view. Mitigation of views may be provided by the installation of screening devices. The locations of screening devices will be determined during detail design with consideration given to the findings of this report; public and municipal consultation; and, engineering and property constraints.

These should be derived from traditional fencing and vegetative plantings in keeping with those examples found in the general area. The following list of species may be used for mitigation applications as a mixed vegetated fencerow in areas where resulting tree height will not result in shading of the solar panels.

Recommended Trees:

Red Maple	Acer rubrum
Serviceberry	Amelanchier canadensis*
Sugar Maple	Acer saccharum
Silver Maple	Acer saccharinum
Japanese Dogwood	Cornus kosus*
Pagoda Dogwood	Cornus alternifolia*
Black Walnut	Junglans nigra
Tamarack	Larix laricina
Norway Spruce	<i>Picea abies</i> (Historically planted in rural areas)
White Spruce	Picea glauca
Jack Pine	Pinus banksiana
Red Pine	Pinus resinosa
White Pine	Pinus strobus
Scots Pine	Pinus sylvestris
Red Oak	Quercus rubra
White Oak	Quercus alba
White Cedar	Thuja occidentalis

*Tree Varieties 4.5 m to 9 m in height

Recommended Shrubs:

Silky Dogwood	Cornus amonum
Red Osier Dogwood	Cornus sericea
Scarlet Hawthorn	Crataegus coccinea
Highbush Cranberry	Viburnum trilobum
Nannyberry	Viburnum lentago

Mitigation of potential visual effects on built heritage resources

Although several built heritage resources have been identified through field survey such features will not be demolished or removed as a result of property development for the solar facility. Screening devices may be appropriate at certain locations, such as the area between Properties 14B and 14C, as backdrops to identified features to prevent silhouetting of the built heritage resources against solar facility. As each property is unique, specific site mitigation measures, where required, will be determined during detailed design through consultation with the landowner and with consideration to engineering and property constraints.

3578 Unity Road, adjacent to Property 3

The log structure recorded at this site was moved to this location from elsewhere (Personal communication with owner, September 27, 2011). It does not form part of a property to be developed. No mitigation is required or recommended.

Westbrook Road, Property 12

In the case of Property 12 where the remnants of log structure were identified this should be noted for potential archaeological mitigation. The remnant structure is rightly described as a "ruin" and falls under the purview of archaeology as defined in Subsection 1(2) of Ontario Regulation 359/09.

4017 Unity Road, Land located between Property 14B and 14C

The stone farmhouse and frame barn are located between two properties identified as solar energy project sites and are not anticipated to be demolished or removed as part of this project. If the adjacent properties are to be developed attention should be given to addressing edge treatments or buffer and screening devices around the periphery of these features to filter or break up views to any solar energy facility beyond. The locations and type of treatment, if required, will be determined in consultation with the landowner and with consideration of engineering and property constraints. The following list of species would be recommended for any future mitigation applications and to be installed as a mixed vegetated fencerow with the inclusion of cedar rail fencing where required by landowner agreements.

Recommended Trees:

Red Maple	Acer rubrum
Sugar Maple	Acer saccharum
Serviceberry	Amelanchier canadensis*
Japanese Dogwood	Cornus kosus*
Pagoda Dogwood	Cornus alternifolia*
Tamarack	Larix laricina

Norway Spruce	Picea abies
White Spruce	Picea glauca
White Pine	Pinus strobus
Scots Pine	Pinus sylvestris
Red Oak	Quercus rubra
White Cedar	Thuja occidentalis

*Tree Varieties 4.5 m to 9 m in height

Recommended Shrubs:

Silky Dogwood	Cornus amonum
Red Osier Dogwood	Cornus sericea
Scarlet Hawthorn	Crataegus coccinea
Highbush Cranberry	Viburnum trilobum
Nannyberry	Viburnum lentago

5.0 RECOMMENDATIONS

It is recommended that in any development or construction management plan developed for the subject properties that appropriate mitigation strategies be adopted to address the potential impacts or effects of solar facility as noted in Section 4.

The Ministry is satisfied with these recommendations.

This letter does not waive any requirements which you may have under the *Ontario Heritage Act*. Also, this letter does not constitute approval of the renewable energy project. Approvals of the project may be required under other statutes and regulations. It is your responsibility to obtain any necessary approvals or licences.

Please feel free to contact me if you have questions or require additional information.

Sincerely,

Laura Hatcher Heritage Planner

cc. Rob Young, Associate Environmental Scientist, Power Sector Co-Lead AMEC

David Cuming, Managing Co-ordinator, Cultural Heritage Planning MHBC

Chris Schiller, Manager, Culture Services Unit Ministry of Tourism and Culture

^{*} In no way will the Ministry be liable for any harm, damages, costs, expenses, losses, claims or actions that may result: (a) if the Report(s) or its recommendations are discovered to be inaccurate, incomplete, misleading or fraudulent; or (b) from the issuance of this letter. Further measures may need to be taken in the event that additional artifacts or heritage resources are identified or the Report(s) is otherwise found to be inaccurate, incomplete, misleading or fraudulent.